



VEH Photo #13 - View of Right Rear Tag-Axle Wheel With Broken Disc Brake Carrier in Hand Hole (Source: Dallas County Sheriff's Dept.)